


# CORNER RECORD

COUNTY OF INYO / MND T. 546 S. R. 37E M.D.B. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER ☒ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐  
 CORNER IDENTIFICATION - DATE OF VISIT 3-22 1978



CORNER - LEFT AS FOUND ☒ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 2" Iron Pipe 0.6'± above ground and in a mound of rock  
2.5'± in diameter and 1'± high with 2"x2" hub in pipe with  
L.S. Tag # 3238. Corner is 500'± South of Creek and 120'±  
WSW of point of small hill that is just a few feet higher  
than the corner. Corner is 3/4 mile± West of State Route 168.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


Original Corner post  
(3" x 2.5'±) and squared off on one end is lying in rock mound.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐

STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION \_\_\_\_\_ STATION \_\_\_\_\_

ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)



## SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY  
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT  
 ON March 22 1978

SIGNED: John P. [Signature]

L.S. or R.C.E. No. 4418

SEAL

## COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19\_\_\_\_  
 AND EXAMINED AND FILED \_\_\_\_\_ 19\_\_\_\_

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No. 1537-33-5

STATEMENT ON BACK OF SHEET

YES ☐ NO ☐